



# HA87301974 KIT [OSRAM LED Cab Warning Light Kit for Case IH Tractors]

## Instruction Guide

1. Remove OE light from cab by removing two screws from bottom of light
2. Disconnect electrical connector from OE light and remove from cab
3. Attach electrical connector from new Hy-Cap light
4. Place new Hy-Cap light into cab and insert screws
5. Secure hardware

### NOTE:

When replacing cab lights on Quadtrac or 4WD machines, a jumper must also be installed. Jumpers are included with light.

